

PROCESSING COPY

## INFORMATION REPORT INFORMATION REPORT

## CENTRAL INTELLIGENCE AGENCY

This material contains information affecting the National Defense of the United States within the meaning of the Espionage Laws, Title 18, U.S.C. Secs. 793 and 794, the transmission or revelation of which in any manner to an unauthorized person is prohibited by law.

SECRET

25X1

COUNTRY

Hungary

REPORT

SUBJECT

Transzformator és Villamoskészlekgyar,  
Budapest

DATE DISTR.

30 MAR 1957

25X1

NO. PAGES

1

REQUIREMENT  
NO.

RD

REFERENCES

25X1

DATE OF  
INFO.PLACE &  
DATE ACQ.

ENCLOSURE ATTACHED  
PLEASE ROUTE

SOURCE EVALUATIONS ARE DEFINITIVE. APPRAISAL OF CONTENT IS TENTATIVE.

25X1

report concerning the Transzformator es Villamoskészlekgyar, Budapest. The report gives a list of products of the enterprise, a list of the materials which were in short supply and therefore were the cause of poor quality of the products, and it states that craftsmen were scarce and the workers were generally dissatisfied with the Communist Party and the government. The report also includes a list of important personnel at the enterprise, The report also includes the following sketches, with explanatory legends:

- Layout of the enterprise, showing the location of the various departments.
- Layout of the Management Buildings block, showing the location of the various offices and sections.
- Layout of the Main Factory Buildings, showing the location of the various offices and sections.

25X1

25X1

SECRET

STATE	X	ARMY	X	NAVY	X	AIR	X	SEC	X	AEC					
-------	---	------	---	------	---	-----	---	-----	---	-----	--	--	--	--	--

(Note: Washington distribution indicated by "X", Field distribution by "#".)

INFORMATION REPORT INFORMATION REPORT

**SECRET****SECRET**HUNGARYEconomic/Scientific

25X1

TRANSFORMATOR ES VILLALÉSI SZÜLLŐGYÁR, BUDAPEST.

25X1

1. Attached as Appendix I is a plan of the above factory.  
 Appendix II is the detail of the Management Block shown in Appendix I.  
 Appendix III is the detail of the Main Factory Building shown in Appendix I.  
 At Appendix IV is a list of factory personnel

25X1

2. The following is a list of products : -

1. Instrument Transformers

1 KV range

Type "AL10", about 400 per month.

10 KV range

Type "ADP" looped wire type, porcelain insulated  
 about 200 per month

Type "ARP" bar type, about 100 per month

Type "AP" porcelain insulated

Type "AL 10 c" porcelain insulated

Prototype for cross-hole type.

2. Voltage transformers.

1 KV range

Dry Type, air insulated.

10 - 20 KV range

Dry type, porcelain insulated

3. Small oil circuit-breakers.

6 KV, 600 Amp.

1a) Type "VIG" Russian model for coal mines.

b) Type "VIG,133".

c) Type "SLOVENSKÝ" hand and spring operated.

20 - 30 KV

Hand operated only.

4. Large oil circuit-breaker.

10, 20, 30 KV

Both indoor and outdoor types.

5. Sectionalizers (sic)

1, 10, 20, 30, KV - 200,400,600,1000,1500, 2000, 3000 Amp.

10 KV - 4000 Amp.

6. High Voltage Fuses.

3, 6, 10, 20, 30 KV - 2,4,6,10,15,25,40,60,100 Amps.

7. Pedal resistance for sewing machines, 15000 per month

8. Wire wound potentiometers

WT 400, WT 900

**SECRET CONTROL****RI COPY****U. S. EYES ONLY**

25X1

9. Direct current delay and relay. type FIR 3.

**SECRET**

25X1

10. Push buttons.

11. Pilot lamps

12. Auxiliary switches

13. Exciters.

14. Automatic control panels for ships

15. Lifts.

16. Controls for mines, steel plants etc.

17. Small power transformers 1000 to 5000 VA types.

18. Metal-clad circuit breakers in 10 KV range.

3. The quality of the products was very poor for the following reasons :

- a) shortage of supply of copper, good quality steel and enamelled wires.

- b) lack of craftsmen

- c) general dissatisfaction among the workers with the Communist Party and the Government.

4. About 10% of the factory's production went for export.

**SECRET**

25X1

**SECRET**  
**U. S. OFFICIALS ONLY**

25X1

**SECRET**

25X1

Personnel connected with : -

25X1

TELENSFORMATION ES VILLAMSKISZULANCYAR.  
Budapest.

Director - Endre KRALI,

25X1

Chief Engineer - Albert HOLZHAUSER.

Secretary of the Communist Party in the Factory - George KISS.

25X1

Personnel Manager - Bela FEJES.

Head of Drawing Office - Geza HATDEGG.

Head of Engineering Department - Alexander PAP.

Factory Manager - Kalman DORNA.

25X1

Chief Inspector - Stephan TALOSI.

Head Cashier - Ferenc VEGSZENDROY.


Chief of Planning Department - Stephan ALBERT.

**SECRET**

25X1

**SECRET CONTROL**  
**U. S. OFFICIALS ONLY**

## APPENDIX I



TRANSZFORMATOR ES VILLAMESKESZULEKGYAR.


## LEGEND :

1. Joiners' workshop
2. Garage
3. Building material and caretaker
4. Steel cutting workshop, with store at back
5. Personnel Department ("Fekete").
6. New building under construction, purpose not known.
7. Time study office.
8. Cashier and pay office.
9. Sheet metal workshop.
10. Store for finished products.
11. Firstaid post.
12. Galvanising workshop
13. Testing room.
14. Testing room.
15. Oil circuit breaker workshop.
16. Paint shop.
17. Laboratory, Experimental Department. This has an underground section.




SECRET CONT  
U. S. OFFICE

## APPENDIX II

25X1



GROUND FLOOR


1<sup>ST</sup> FLOOR2<sup>ND</sup> FLOOR3<sup>RD</sup> FLOORLEGEND:

1. Main staircase
2. Main drive through for cars
3. Main hall.
4. Caretaker
5. Factory police
6. Automatic control cabinet assembly.
7. Canteen, kitchen and service.
8. Canteen.
9. Library
10. Young workers committee (D.I. SZ).
11. Workers' committee.
12. Drawing Office.
13. Director's room.
14. Director's and Chief Engineer's secretaries.
15. Chief Engineer's room.
16. Secretary of the Communist party for the factory.
17. Theatre.

BY COPY

SECRET  
U. S. OFFICIALS ONLY




25X1



GROUND FLOOR



25X1

1<sup>st</sup> FLOOR2<sup>nd</sup> FLOOR3<sup>rd</sup> FLOOR.LEGEND

1. Automatic controls
2. Ovens for varnishing
3. Tool room.
4. Small oil volume circuit breakers. 6 - 35 KW.
5. Testing room for 4. above.
6. Planning (Dr. Alberti).
7. Factory Management (DORKA)
8. Print room.
9. Methods and technical development (PAP and SIRATO)
10. Sales (LAMBING)
11. Contractors, push buttons, pilot lamps, resistances, relays
12. Sectionalizers (outdoor & indoor) high voltage fuses.
13. Motor and drives for circuit breakers.
14. Plastics laboratory.
15. Store.
16. Test room for instrument transformers.
17. Voltage transformers.
18. Current transformers.
19. Small power transformers ( up to 1000 V.)
20. Tool and jig design.

**SECRET**  
U. S. GOVERNMENT

**RE COPY**